

DAMAGE REPORT

Inbound carrier: MAX SCHULTE
MASH550S 550S 10-Dec-2025 05:53

Container	Damage type	Damage location
MSKU5755284	BENT	LEFT
MRSU7822314	CUT	RIGHT
MRSU7822314	HOLE	RIGHT
CAAU2278535	BENT	RIGHT
CAAU2278535	BENT	BOTTOM
HASU1254963	DENT	CORNER
CAIU2593890	BENT	BOTTOM
CAIU2593890	DENT	CORNER
HLXU1286570	DENT	DOORSYSTEM
MRKU9021728	BENT	LEFT
MRKU9021728	BENT	BOTTOM
MRKU9021728	BENT	RIGHT
MRKU8968810	DENT	LEFT
MRKU8725147	DENT	LEFT
MRKU7811657	DENT	CORNERPOST
MRKU7811657	BENT	FRONT
MRKU7811657	BENT	BOTTOM
MRKU7811657	DENT	LEFT
UETU5940205	BENT	RIGHT
UETU5940205	BENT	LEFT
MRSU3107956	DENT	LEFT
GAOU7083121	DENT	RIGHT
GESU1407649	DENT	FRONT
UETU8053518	DENT	RIGHT
MRKU3032197	BENT	RIGHT
MRKU3032197	BENT	LEFT
MRKU3032197	DENT	FRONT
MRKU3032197	BENT	FRONT

*Container was not reported
to duty officer
For receipt only
Discharge as loaded*


Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
HLXU1343618	DENT	FRONT
HLXU1343618	BENT	BOTTOM
MAEU3484924	RIPPED	TARPAULIN
CNIU2231158	DENT	RIGHT
TCNU3360346	DENT	RIGHT
MRSU4593868	DENT	LEFT
MRSU4593868	BENT	LEFT
UETU2781218	DENT	LEFT
MRKU9893870	DENT	LEFT
MRKU3771242	BENT	RIGHT
CAXU5555920	CUT	TARPAULIN
HLBU8174683	CUT	TARPAULIN
SEKU1491052	DENT	RIGHT
HLBU8292069	CUT	TARPAULIN
HLBU3832288	DENT	DOORSYSTEM
UETU5461624	DENT	CORNERPOST
MRKU3313527	DENT	FRONT
MRKU3313527	DENT	RIGHT
MRKU3313527	BENT	LEFT
OOLU5825676	DENT	RIGHT
MSKU8873737	DENT	RIGHT
HAMU2621505	DENT	LEFT
BEAU5102297	DENT	DOOR
BEAU5102297	DENT	CORNERPOST
MRKU4231547	DENT	RIGHT
MRKU4231547	DENT	LEFT
MRKU4231547	DENT	FRONT
MRKU3762770	DENT	RIGHT
MRKU3762770	DENT	FRONT
MRKU3762770	BENT	LEFT
TCKU7320270	DENT	LEFT
TCNU2572490	DENT	LEFT
SEKU6865936	DENT	RIGHT
MRKU0798717	DENT	FRONT





Container was not reported
to duty officer
For receipt only
Discharge as loaded


Container	Damage type	Damage location
MRKU0798717	DENT	RIGHT
MRKU0798717	DENT	LEFT
HASU4460654	DENT	LEFT
MAEU3508498	RIPPED	TARPAULIN
TCLU4300318	DENT	RIGHT
TCLU4300318	BENT	LEFT
OOLU7908954	BENT	RIGHT
OOLU7908954	BENT	LEFT
MRSU4372851	DENT	LEFT
MMAU1086472	DENT	RIGHT
MMAU1086472	DENT	LEFT
STJU2032639	DENT	CORNERPOST
HLBU3250245	DENT	RIGHT
TCKU7277451	DENT	LEFT
HLBU8312967	CUT	TARPAULIN
MRKU3540958	DENT	LEFT
MRSU5850214	BENT	RIGHT
MRSU5850214	BENT	LEFT
TCNU3428235	DENT	RIGHT
UACU4154444	BENT	BOTTOM
FCIU6554627	BENT	RIGHT
MRSU5837737	DENT	RIGHT
MRSU3442532	DENT	LEFT
MRSU3442532	DENT	FRONT
MAEU4688922	CUT	TARPAULIN
MAEU4661304	CUT	TARPAULIN
MAEU4655087	CUT	TARPAULIN
CAXU5563227	RIPPED	TARPAULIN
MAEU4694904	CUT	TARPAULIN
MRKU4233302	DENT	RIGHT
MRKU4233302	BENT	LEFT
MAEU4654460	CUT	TARPAULIN
UACU5811543	DENT	RIGHT
UACU5811543	DENT	LEFT



Container was not reported
to duty officer. For receipt only
Discharge as loaded



Container	Damage type	Damage location
MAEU3515497	RIPPED	TARPAULIN
MAEU3515497	RIPPED	TARPAULIN
MAEU3434435	RUSTED	TARPAULIN
HLBU1321890	DENT	RIGHT
HLBU1321890	BENT	RIGHT
HLBU1321890	BENT	LEFT
MAEU3430677	RIPPED	TARPAULIN
HLBU8160859	CUT	TARPAULIN
MRSU5867480	DENT	LEFT
MRSU5867480	DENT	FRONT
MSKU9970515	BENT	LEFT
HASU1301366	BENT	RIGHT
HASU1301366	BENT	BOTTOM
HASU1301366	DENT	LEFT
HASU1301366	BENT	LEFT
MRSU0416550	BENT	LEFT
MRSU0416550	BENT	BOTTOM
CAIU7563414	DENT	LEFT
MRKU4308417	DENT	RIGHT
MNBU3444569	DIRTY	FRONT
MAEU3428052	RIPPED	TARPAULIN
MAEU3428052	BROKEN	DOOR
HASU1353950	DENT	RIGHT
SEGU2702793	DENT	FRONT
MOFU0621081	DENT	FRONT
MRKU4634429	BENT	LEFT
MRKU4634429	BENT	RIGHT
MRKU4634429	BENT	BOTTOM
HASU5073921	DENT	FRONT
HASU5073921	BENT	RIGHT
HASU5073921	BENT	LEFT
MRSU7833073	DENT	LEFT
SUDU7791828	DENT	LEFT
SUDU7791828	BENT	RIGHT



Containers was not reported
to duty officers
For receipt only
Discharge as loaded

Page 4 of 14
Without any liability accepted
Constanta South Container Terminal
Planning Department


Container	Damage type	Damage location
SUDU7791828	BENT	BOTTOM
SUDU7791828	DENT	CORNERPOST
SEGU5469319	HOLE	TOPROOF
BMOU6634895	DENT	LEFT
MRKU3624724	DENT	LEFT
MRKU4147879	DENT	RIGHT
MRKU4147879	BENT	RIGHT
MRKU4147879	BENT	LEFT
TLLU2053900	DENT	RIGHT
MAGU2324889	BENT	BOTTOM
MAGU2324889	DENT	RIGHT
HLXU8361125	RUSTED	BACK
HLXU8361125	RUSTED	FRONT
HLXU8361125	BENT	RIGHT
HLXU8361125	RUSTED	RIGHT
HLXU8361125	BENT	LEFT
DFSU6306820	DENT	LEFT
GLDU5724627	DENT	FRONT
GLDU5724627	BENT	RIGHT
GLDU5724627	BENT	BOTTOM
GLDU5724627	BENT	LEFT
MSKU1450918	BENT	RIGHT
HLXU1352013	BENT	LEFT
HLXU1352013	BENT	FRONT
HLXU1352013	DENT	FRONT
HLXU1352013	BENT	RIGHT
HLXU1352013	DENT	RIGHT
HLXU1352013	BENT	BOTTOM
TGCU2109941	DENT	LEFT
HLBU1498382	DENT	LEFT
HLBU1498382	BENT	BOTTOM
TCLU2841329	DENT	FRONT
TCLU2841329	BENT	BOTTOM
MRKU5509669	DENT	FRONT

Containers was not reported
to duty officers
For receipt only
Discharge as loaded





Container	Damage type	Damage location
MRKU5509669	DENT	RIGHT
MRKU5509669	BENT	LEFT
FSCU7096580	DIRTY	RIGHT
MRSU5745800	DENT	FRONT
MRKU5074904	DENT	RIGHT
MRKU5074904	DENT	LEFT
HAMU1243139	BENT	LEFT
MRKU2005793	CUT	FRONT
MRSU4477390	DENT	LEFT
MRKU6424951	DENT	LEFT
MSKU9883642	BENT	RIGHT
MSKU9883642	DENT	RIGHT
MSKU9883642	BENT	LEFT
FANU1770384	BENT	RIGHT
FANU1770384	SCRATCHED	RIGHT
FANU1770384	BENT	LEFT
MRSU4531969	DENT	RIGHT
MRKU4735379	BENT	RIGHT
MRKU4735379	DENT	RIGHT
MRKU4735379	DENT	LEFT
MRKU4146614	DENT	LEFT
GLDU5785448	BENT	FRONT
GLDU5785448	DENT	CORNERPOST
GLDU5785448	BENT	RIGHT
GLDU5785448	CUT	GASKET
GLDU5785448	BENT	LEFT
MSKU1853575	BENT	RIGHT
MSKU1853575	DENT	RIGHT
MSKU1853575	BENT	LEFT
MRSU7827363	BENT	RIGHT
TCLU5684429	BENT	LEFT
MRKU2781061	DENT	FRONT
MRKU2781061	BENT	RIGHT
MRKU2781061	BENT	LEFT

Container was not reported
to duty officer
For receipt only
Discharge as loaded



Container	Damage type	Damage location
BSIU9011791	BENT	FRONT
BSIU9011791	BENT	RIGHT
BSIU9011791	BENT	LEFT
BSIU9011791	DENT	LEFT
BSIU9011791	DENT	FRONT
BSIU9011791	CUT	LEFT
FANU1996900	IMO LABEL	DOOR
FANU1996900	IMO LABEL	FRONT
TRHU2287795	BENT	RIGHT
TRHU2287795	BENT	LEFT
TRHU2287795	BENT	BOTTOM
QNNU1238127	CUT	TARPAULIN
HLBU9166830	DENT	RIGHT
CAAU5225797	BENT	RIGHT
MNBU9009147	DENT	RIGHT
UACU6065623	DENT	LEFT
UAEU1237692	DENT	LEFT
MAEU3437500	DENT	BOTTOM
HLBU1411063	BENT	RIGHT
HLBU1411063	BENT	LEFT
UACU4786641	BENT	LEFT
CAAU6091590	DENT	LEFT
MRKU9185022	DENT	BACK
MAEU3422136	RIPPED	TARPAULIN
MSKU1389443	DENT	LEFT
MRSU3332860	DENT	RIGHT
MRSU3332860	BENT	RIGHT
MRSU3332860	DENT	FRONT
MRSU3332860	DENT	LEFT
TCLU6424935	DENT	RIGHT
TCLU6424935	DENT	FRONT
MRSU5951360	DENT	RIGHT
MSKU0822862	BENT	LEFT
TGHU5067529	BENT	LEFT

Containers was ~~too~~ not
informed to duty officer
For receipt only.
Discharge as loaded.



Container	Damage type	Damage location
HASU1079330	BENT	BOTTOM
MRSU8163037	BENT	LEFT
CAIU8534792	DENT	LEFT
MRSU6032995	DENT	RIGHT
MRSU6032995	BENT	LEFT
MRSU6032995	DENT	LEFT
TGBU5684679	BENT	RIGHT
TGBU5684679	BENT	LEFT
HLBU2396301	DENT	LEFT
MRKU6741149	DENT	LEFT
MRSU6339791	DENT	RIGHT
UETU7588942	BENT	RIGHT
TCLU8565233	DENT	RIGHT
MRKU5617982	DENT	RIGHT
MRKU5617982	DENT	LEFT
MRKU0507581	BENT	FRONT
MRKU0507581	DENT	RIGHT
MRKU0507581	DENT	DOORSYSTEM
MRKU0507581	DENT	LEFT
MRKU0507581	BENT	LEFT
CAIU4228881	BENT	LEFT
MSKU1377118	BENT	LEFT
TLLU1551386	RIPPED	TARPAULIN
TLLU1551386	IMO LABEL	FRONT
CAXU5547313	RIPPED	TARPAULIN
MRKU4951125	CUT	FRONT
MRKU4951125	HOLE	FRONT
MRKU4951125	BENT	RIGHT
MRKU4951125	BENT	LEFT
MRKU9514792	BENT	RIGHT
MRKU9514792	BENT	BOTTOM
MRKU9514792	BENT	LEFT
CAIU6646324	DENT	LEFT
TCNU2835750	DENT	LEFT

Container was not
informed to duty officer
For receipt only
Discharge as loaded



Page 8 of 14
Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
HLBU8093724	CUT	TARPAULIN
HLBU8225271	CUT	TARPAULIN
MSKU7301932	CUT	FRONT
MRKU3970542	BENT	RIGHT
MRSU3240249	BENT	RIGHT
MRSU3240249	DENT	LEFT
MRSU3240249	BENT	LEFT
MRKU6188049	BENT	LEFT
CAIU2423575	DENT	DOORSYSTEM
CAIU2423575	CUT	DOOR
CAIU2423575	CUT	BACK
CAIU2423575	DENT	LEFT
CAIU2423575	DENT	FLOOR
MRSU0552834	BENT	LEFT
MAEU4675587	CUT	TARPAULIN
MRKU2966810	BENT	RIGHT
MRKU2966810	BENT	LEFT
MRKU2966810	DENT	LEFT
MRKU2966810	CUT	FRONT
UACU5970695	BENT	LEFT
UACU5970695	DENT	FLOOR
MRKU9923888	DENT	FRONT
HASU4903731	HOLE	TOPROOF
TCNU7014383	DENT	LEFT
BSIU8292647	BENT	LEFT
UASU1028300	DENT	RIGHT
TEMU5919222	DENT	FRONT
TEMU5919222	DENT	RIGHT
TEMU5919222	BENT	BOTTOM
HAMU2443018	CUT	DOOR
BEAU4709619	DENT	LEFT
MAGU2547537	BENT	RIGHT
MAGU2547537	BENT	LEFT
MRSU4225974	DENT	RIGHT

Duty officer was not
informed

Discharge as loaded



Page 9 of 14
Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU7022687	DENT	FRONT
GCXU2343763	BENT	LEFT
GCXU2343763	BENT	RIGHT
HLBU3715677	DENT	DOORSYSTEM
FSCU8081163	BENT	LEFT
FSCU8081163	BENT	RIGHT
MRSU4378443	BENT	LEFT
CAAU9236402	DENT	RIGHT
HLBU2479324	BENT	LEFT
MSKU1375500	DENT	LEFT
FFAU5771390	DENT	LEFT
NIDU2313664	BENT	LEFT
FANU3182939	DENT	LEFT
MRKU8504779	BENT	BOTTOM
MRKU8504779	DENT	RIGHT
UACU3990476	BENT	BOTTOM
TEMU1860574	DENT	LEFT
UACU3836938	DENT	FRONT
UACU3836938	DENT	CORNERPOST
UACU3836938	BENT	BOTTOM
UACU3836938	DENT	LEFT
DFSU6535169	DENT	RIGHT
MMAU1069963	DENT	RIGHT
SUDU6191027	DENT	RIGHT
SUDU6191027	DENT	LEFT
MRKU9309838	BENT	RIGHT
MRKU9309838	BENT	LEFT
MRKU9309838	DENT	FRONT
SEKU6947295	BROKEN	BOTTOM
SEKU6947295	DENT	FRONT
UACU2418091	CUT	TARPAULIN
TCKU7124410	HOLE	TOPROOF
TCKU7124410	HOLE	TOPROOF
MSKU1954971	DENT	LEFT

Duty officer was
not informed
Discharge as loaded



Page 10 of 14
Without any liability accepted
Constantia South Container Terminal
Planning Department

Container	Damage type	Damage location
HAMU1375270	DENT	RIGHT
SUDU6740908	DENT	RIGHT
MRSU3795735	DENT	LEFT
TGBU5365202	DENT	LEFT
MRSU4846380	DENT	LEFT
TCKU6567501	DENT	LEFT
CAAU8476395	DENT	LEFT
FANU1398261	DENT	RIGHT
FANU1398261	DENT	LEFT
FFAU1333420	DENT	RIGHT
MAEU3437080	BROKEN	DOOR
MRKU2029075	DENT	RIGHT
MRKU2029075	DENT	LEFT
TRLU7635464	DENT	RIGHT
TRLU7635464	BENT	LEFT
TRLU7635464	DENT	LEFT
CAIU8041950	RUSTED	FRONT
CAIU8041950	RUSTED	BACK
CAIU8041950	BENT	RIGHT
CAIU8041950	BENT	FRONT
MRSU6896652	DENT	RIGHT
MRSU6896652	DENT	LEFT
MRSU6896652	BENT	LEFT
MRSU3356650	BENT	LEFT
HAMU3159921	DENT	RIGHT
HAMU3063563	BENT	LEFT
MRKU4064141	BENT	RIGHT
MRKU4064141	BENT	LEFT
MRKU4064141	CUT	LEFT
HLBU3321919	DENT	RIGHT
SUDU8834159	DENT	LEFT
HLXU3508276	DENT	FRONT
HLXU3508276	BENT	BOTTOM
HLXU3508276	BENT	LEFT

Duty officer was
not informed
Discharge as loaded

Page 11 of 14
Without any liability accepted
Constanta South Container Terminal
Planning Department



Container	Damage type	Damage location
CAAU6082807	BENT	RIGHT
HLBU1965065	DENT	LEFT
HLBU1623437	DENT	RIGHT
HLBU1623437	DENT	LEFT
MRKU3327650	DENT	LEFT
MRKU2447286	DENT	LEFT
CAIU8043886	DENT	LEFT
HLXU3613944	CUT	TARPAULIN
GCXU2524674	BENT	RIGHT
MRKU2539844	DENT	RIGHT
MRKU2539844	DENT	FRONT
MRKU2539844	DENT	LEFT
MRKU2539844	BENT	LEFT
UACU3941091	DENT	RIGHT
UACU3941091	BENT	BOTTOM
UACU3941091	DENT	LEFT
MRSU8522219	DENT	CORNERPOST
SEGU5634368	DENT	LEFT
TRHU1498432	DENT	RIGHT
TRHU7597387	BENT	LEFT
HLBU1583479	DENT	RIGHT
HLBU1583479	DENT	FRONT
HLBU1583479	DENT	LEFT
TXGU7157941	BENT	FRONT
TXGU7157941	BENT	RIGHT
TXGU7157941	DENT	LEFT
TXGU7157941	BENT	LEFT
AXIU1472815	DENT	LEFT
MAEU3417818	IMO LABEL	RIGHT
MAEU3417818	BROKEN	DOOR
HLBU1766192	DENT	LEFT
MSKU1282917	DENT	RIGHT
MSKU1322630	DENT	LEFT
HLBU8023780	CUT	TARPAULIN

Duty officer was
not informed
Discharge as loaded


Page 12 of 14

Without any liability accepted
Constanta South Container Terminal
Planning Department



Container	Damage type	Damage location
MSKU1495738	CUT	LEFT
MRKU8614204	DENT	RIGHT
MRKU8614204	DENT	FRONT
FCIU9717939	DENT	FRONT
FCIU9717939	DENT	RIGHT
FCIU9717939	DENT	LEFT
MRKU0639227	BENT	RIGHT
MRKU0639227	DENT	LEFT
PONU0664746	DENT	FRONT
PONU0664746	BENT	BOTTOM
PONU0664746	DENT	LEFT
CLHU9115830	DENT	LEFT
MRSU6289432	DENT	LEFT
MRKU5553445	BENT	RIGHT
MRKU5553445	BENT	LEFT
MRKU5553445	DENT	LEFT
HLBU1867691	TORN	DOORSYSTEM
TRHU6216207	DENT	LEFT
MRKU5914281	DENT	RIGHT
HASU4392082	DENT	RIGHT
HASU4392082	BENT	LEFT
MIEU0042437	BENT	LEFT
MSKU0898277	DENT	LEFT
MAEU3414742	RIPPED	TARPAULIN
MAEU3410990	RIPPED	TARPAULIN
PCLU4601895	DENT	RIGHT
HLBU3109371	DENT	LEFT
CAAU5957566	BENT	RIGHT
GCXU5940850	DENT	RIGHT
GCXU5940850	BENT	RIGHT
GCXU5940850	DENT	LEFT
MRKU3651735	DENT	LEFT
UETU2207175	DENT	RIGHT
HLBU2177793	DENT	LEFT

Duty officer was
not informed
Discharg as loaded



Container

Damage type

Damage location

MAEU4679670

CUT

TARPAULIN

MRSU4274726

BENT

LEFT

MRSU5037312

BENT

LEFT

Duty officer was not
informed

Discharge as loaded

