

Customer Advisory

Implementing of Container Cleaning Charge: MITT (Thilawa) Terminal

28th May 2021

Dear Customer,

In order to fulfil a surge demand for empty containers service at MITT (Thilawa) terminal and keep providing you with our best services **Maersk Group in Myanmar will implement a container cleaning charge effective from 1st July 2021 at MITT (Thilawa) terminal** same as other of our service location.

For many years, our customers have been exploring options for return empty containers at MITT terminal to support their supply chain base on location wise.

With a surge in demand for empty container return by Importers and empty container pick up by Exporters at MITT (Thilawa) terminal. In order to comply with the requirement and provide a best fit containers condition to support the trade needs.

Hence one of depot activities as **"on-dock repair"** operating by Maersk's experienced service provider named Bespoke service will be provide at MITT (Thilawa) Terminal.

Bespoke service will direct collect cleaning fee based on the empty container return conditions/usage by Importer for all container return at MITT (Thilawa) terminal.

There might be a few difference cleanings services as list below, which may subject to difference cost.

- Normal Cleaning
- Chemical Cleaning
- Special Cleaning
- Heavy damage, Etc.

Standard cost and type enclose for your reference.

If you have any questions or concerns, please reach out to your local Maersk representative or contact

Sincerely,
Maersk



BESPOKE SERVICE CO.,LTD

Container Repair & Modification

No. 360, Mya Yadanar Housing, Ayeyarwaddy Street, Aye Myitta Quarter,
Thanlyin Township, Yangon, Myanmar.

Tel : 09 250 570 080, 09 795 919 465
Email : thanhtutstar@gmail.com, bespokeservicecoltd@gmail.com,

CONTAINER REPAIRING CHARGES QUOTATION FOR CONSIGNEE / CUSTOMERS

Date: 24/05/2021

SR.	DAMAGE DESCRIPTION	DIMENSION	AMOUNTS (KS)
1	NORMAL WASHING	20FT CONTAINER	10,000
2	CHEMICAL WASHING		15,000
3	SPECIAL WASHING		23,000
4	NORMAL WASHING	40FT CONTAINER	20,000
5	CHEMICAL WASHING		30,000
6	SPECIAL WASHING		46,000
7	DOOR GASKET CUT	300 MM	10,000
8	PUSH IN & PUSH OUT	300MM x 300MM	5,000
9	ANY PANEL - CUT	UNDER 300MM	10,000
10	ANY PANEL - HOLE	UNDER 150MM	10,000
11	DOOR PANEL - CUT & HOLE	300MM	20,000
12	LOCKING BAR - REPLACE	1NOS	30,000
13	LOCKING BAR - BENT & CUT	1NOS	10,000
14	LOCKING BAR BRACKET - BENT & CUT	1PCS	10,000
15	LOCKING BAR CAMP & KEEPER - BENT & CUT	1PCS	10,000
16	HANDLE BAR - REPLACE	1NOS	15,000
17	HANDLE BAR - BENT & CUT	1NOS	10,000
18	HANDLE BAR RETAINER - BENT & CUT	1PCS	10,000
19	FRONT SILL - BENT & CUT	300MM	35,000
20	FRONT HEADER - BENT & CUT	300MM	35,000
21	REAR SILL - BENT & CUT	300MM	35,000
22	REAR HEADER - BENT & CUT	300MM	35,000
23	TOP RAIL - BENT & CUT	300MM	30,000
24	BOTTOM RAIL - BENT & CUT	300MM	35,000
25	CROSS MEMBER - BENT & CUT	1NOS	50,000
26	CORNER POST - BENT & CUT	300MM	50,000
27	CORNER CASTING - BENT & CUT	1PCS	50,000
28	VENTILATION COVER - REPLACE	1PCS	15,000
29	FLOOR DENTED & BROKEN	1200MM x 800MM	40,000
30	FLOOR DENTED & BROKEN	1200MM x 1200MM	80,000
31	FLOOR DENTED & BROKEN	1200MM x 2400MM	160,000
32	DOOR HINGE - BENT & CUT	1PCS	25,000
33	J-BAR - BENT & CUT	300MM	10,000
34	DECALS- REPLACE - UP TO FOUR LETTERS (PREFIX)	1PCS	10,000
35	DECALS - REPLACE - UP TO THREE DIGITS (UNMBER)	1PCS	10,000
36	DECALS - REPLACE - CONTAINER CHECK DIGIT	1PCS	15,000
37	DECALS - REPLACE - UIC DECAL	1PCS	10,000

Effected date from 01/01/2021 to 31/12/2021

Remark: 1) Consignee/Customers need to pay 5%Tax on repairing charges.
2) Above rates are included the materials and labours cost.



Than Htut
Managing Director
Bespoke Service Co.,Ltd