


# External audits show progress

## SL Meteor - Plot 59 (Y.S. Investments) audit status (No. of findings):



**Note:**

1. In HSE audits conducted by Class Lloyd's Register (LR), the final report includes 'observation', which reflects deviance from best practices and provide LR's view, but are as such not a non-compliance to Maersk RSRs. There were nil observations at the end of recycling of the subject vessel
2. In RP audit, there was 1 open finding related to exceeding overtime working hours, which is a widespread challenge in many industries and geographies with migrant workforce
3. The external audit progress clearly demonstrates that engagement on the ground leads to swift improvements related to RSRs compliance

**There were no open critical findings or major non-conformances at the time of commencement of ship recycling operations of SL Meteor at Plot 59 Y.S. Investments**