

DAMAGE REPORT

Inbound carrier: AS NINA

ASNI409S

409S

06-Mar-2024 02:14

Container	Damage type	Damage location
MSKU0702614	DENT	RIGHT
MRKU9967736	BENT	BOTTOM
MRKU9967736	BENT	LEFT
MRKU8746010	DENT	CORNERPOST
SUDU8917211	DENT	RIGHT
TCLU7147521	CUT	TARPAULIN
MRKU8850998	BENT	BOTTOM
MRKU8850998	BENT	LEFT
MRKU8083725	DENT	RIGHT
MRKU8083725	BENT	BOTTOM
MRKU8083725	DENT	LEFT
TGHU1841513	BENT	BOTTOM
TGHU1841513	DENT	LEFT
HASU1399798	DENT	LEFT
MSKU9461890	DENT	LEFT
MRKU7374979	BENT	LEFT
TCLU6989504	BENT	BOTTOM
MRSU6533528	HOLE	TOPROOF
SUDU6231074	DENT	LEFT
MAEU3435874	CUT	TARPAULIN
MRSU0111886	BENT	LEFT
MRSU0111886	BENT	RIGHT
MSKU5426904	DENT	LEFT
MRKU3731300	BENT	RIGHT
SUDU7312421	BENT	BOTTOM
SUDU7312421	BENT	LEFT
SUDU7312421	DENT	RIGHT
MRKU9790804	DENT	LEFT

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*



Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRSU4552067	DENT	LEFT
MRSU6162999	DENT	RIGHT
MRSU6162999	DENT	LEFT
MRSU4921231	BENT	RIGHT
MAEU4731968	CUT	TARPAULIN
MRKU2444116	HOLE	TOPROOF
MSKU7899059	BENT	BOTTOM
MSKU7899059	BENT	LEFT
MSKU7899059	BENT	RIGHT
HASU1125143	BENT	BOTTOM
HASU1125143	DENT	LEFT
MNBU3145763	DENT	RIGHT
MNBU3145763	DENT	LEFT
TCKU6648305	DENT	RIGHT
TCKU6648305	DENT	LEFT
SUDU8032699	DENT	RIGHT
SUDU8032699	BENT	LEFT
MRKU6721287	BENT	BOTTOM
MRKU6721287	DENT	RIGHT
MRKU6721287	DENT	LEFT
HASU4892405	BENT	BACK
MNBU4099148	DENT	RIGHT
MSKU8688955	DENT	RIGHT
MRKU9480286	DENT	LEFT
PONU8068851	DENT	LEFT
MAEU4718098	CUT	TARPAULIN
MRSU6325421	CUT	LEFT
MSKU6450675	DENT	LEFT
BEAU5753806	DENT	LEFT
MRKU8154156	DENT	LEFT
SUDU2870950	DENT	TARPAULIN
SKIU4012521	BENT	LEFT
MNBU3903420	DENT	FRONT
MRKU3587214	DENT	RIGHT

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

MIV "AS NINA"
IMO
9401178

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU9696125	BENT	BOTTOM
MRKU9696125	DIRTY	RIGHT
MRKU9696125	IMO LABEL	LEFT
MRKU9696125	IMO LABEL	RIGHT
MSKU3994715	BENT	BOTTOM
TTNU1294607	DENT	RIGHT
TTNU1294607	BENT	BOTTOM
TTNU1294607	DENT	LEFT
TTNU1294607	IMO LABEL	RIGHT
TTNU1294607	IMO LABEL	LEFT
MRKU6855619	BENT	BOTTOM
MSKU7998220	BENT	BOTTOM
MSKU7998220	DENT	RIGHT
MSKU7998220	DENT	LEFT
MSKU5634472	BENT	BOTTOM
MSKU5634472	DENT	RIGHT
MSKU5634472	DENT	LEFT
MRKU8904760	BENT	BOTTOM
MRKU8904760	BENT	RIGHT
MRKU8869782	BENT	RIGHT
MRKU8869782	BENT	BOTTOM
MRKU8869782	BENT	LEFT
MRKU8062846	BENT	BOTTOM
MRKU8062846	DIRTY	RIGHT
MRKU8062846	DENT	LEFT
TTNU1061293	BENT	BOTTOM
TTNU1061293	BENT	LEFT
UETU5855227	DENT	LEFT
MRKU9339576	DENT	RIGHT
MRKU5525398	DENT	RIGHT
MRKU5525398	DENT	LEFT
HASU4994937	CUT	DOOR
TGHU1260946	BENT	BOTTOM
TGHU1260946	DENT	RIGHT

Signed for receipt only,
 without prejudice of liability. 9401178
 Discharged same condition as
 loaded.

IMO 9401178

MV "AS NINA"



Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
TGHU1260946	DENT	LEFT
MRKU7778477	BENT	BOTTOM
MRKU7778477	DENT	LEFT
MSKU5269641	BENT	BOTTOM
MSKU5269641	DENT	RIGHT
MSKU5269641	IMO LABEL	LEFT
MSKU5269641	IMO LABEL	RIGHT
MSKU7242634	BENT	BOTTOM
MSKU7242634	DENT	RIGHT
MSKU7242634	DENT	LEFT
MNBU9131561	DENT	RIGHT
MNBU9131561	DENT	LEFT
SUDU6833148	CUT	DOOR
MNBU9155590	DENT	CORNER
MNBU0411730	DENT	RIGHT
MNBU0411730	DENT	LEFT
MNBU3853269	DENT	RIGHT
MNBU3853269	DENT	LEFT
MNBU3246291	DENT	RIGHT
MNBU3246291	DENT	LEFT
MNBU3246291	DENT	CORNER
MRKU7986043	BENT	RIGHT
MRKU7986043	BENT	BOTTOM
MRKU7986043	DENT	LEFT
MRKU9950728	BENT	BOTTOM
MRKU9950728	DIRTY	RIGHT
MRKU9950728	DENT	LEFT
SUDU7506200	BENT	BOTTOM
SUDU7506200	DENT	LEFT
SUDU3966255	BENT	BOTTOM
SUDU3966255	DENT	LEFT
SUDU3966255	DENT	RIGHT
MNBU0409121	DENT	RIGHT
MNBU0409121	DENT	LEFT

*Signed for receipt only
Without prejudice of liability.
Discharged same condition as
loaded.*

AS NINA
IMO
9401178

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
PONU8027533	BENT	RIGHT
MNBU0346321	DENT	RIGHT
MNBU0346321	DENT	LEFT
SUDU5168526	DENT	LEFT
SUDU5168526	DENT	RIGHT
MRKU5172958	DENT	RIGHT
MRKU2380855	DENT	LEFT
PONU8051611	DENT	RIGHT
FSCU9974978	DENT	RIGHT
FSCU9974978	BENT	LEFT
MRKU4708753	DENT	CORNERPOST
TGBU6844750	DENT	CORNERPOST
MSKU8781501	BENT	LEFT
MSKU8781501	BENT	RIGHT
PONU7357417	DENT	LEFT
MRKU4690470	BENT	LEFT
HASU1346205	DENT	RIGHT
SUDU6590407	DENT	RIGHT
TCNU2563225	DENT	RIGHT
MNBU3393266	DENT	RIGHT
HASU1356538	BENT	BOTTOM
FSCU8278511	DENT	RIGHT
MAEU3427082	CUT	TARPAULIN
HASU4056880	DENT	RIGHT
HASU4056880	BENT	LEFT
SUDU1962857	BENT	BOTTOM
SUDU1962857	DENT	RIGHT
SUDU1962857	BENT	LEFT
MSKU7206690	BENT	BOTTOM
MSKU7206690	BENT	RIGHT
MSKU7206690	DENT	LEFT
MNBU3248951	DENT	TOPROOF
MSKU1641318	IMO LABEL	FRONT
MNBU3553220	DENT	RIGHT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

M/V "AS NINA"
 IMO 9381178
 Signed for receipt only,
 without prejudice of liability.
 Discharged same condition as
 loaded.

Container	Damage type	Damage location
MNBU3553220	DENT	LEFT
PONU8265980	DENT	BOTTOM
SUDU6215860	DENT	RIGHT
SUDU6215860	DENT	TOPROOF
SUDU6215860	DENT	LEFT
SUDU1350255	BENT	RIGHT
SUDU1350255	BENT	LEFT
SUDU1350255	BENT	BOTTOM
MRKU9810747	BENT	BOTTOM
MRKU9810747	DENT	LEFT
TCLU0720652	BENT	BOTTOM
TEMU1516759	BENT	BOTTOM
TEMU1516759	BENT	RIGHT
TEMU1516759	DENT	LEFT
MSKU5773647	BENT	RIGHT
MSKU5773647	BENT	LEFT
MAGU2333622	BENT	BOTTOM
MAGU2333622	BENT	RIGHT
MAGU2333622	BENT	LEFT
MSKU5994782	BENT	BOTTOM
MSKU5994782	DENT	RIGHT
MSKU5766592	DENT	RIGHT
MSKU5766592	BENT	BOTTOM
MSKU5766592	BENT	LEFT
MRKU9938888	BENT	BOTTOM
MSKU5483376	BENT	BOTTOM
MSKU5483376	DENT	RIGHT
MSKU5483376	DENT	LEFT
MWCU7006876	DENT	RIGHT
MWCU7006876	DENT	LEFT
MNBU9062218	BENT	RIGHT
MNBU9062218	DENT	RIGHT
MNBU9062218	DENT	LEFT
MRKU2339764	DENT	RIGHT

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*



*Without any liability accepted
Constanta South Container Terminal
Planning Department*


Container	Damage type	Damage location
MNBU0437904	DENT	RIGHT
MNBU0437904	DENT	LEFT
MRKU2611086	DENT	LEFT
MSKU9342592	BENT	RIGHT
MRKU2086814	DENT	LEFT
MSKU4318850	BENT	BOTTOM
MSKU4318850	DENT	RIGHT
MSKU4318850	DENT	LEFT
MRKU9315321	DENT	RIGHT
MRKU9315321	DENT	CORNER
MRKU9315321	BENT	BOTTOM
MRKU9315321	DENT	LEFT
TRLU9056266	BENT	RIGHT
TRLU9056266	BENT	BOTTOM
TRLU9056266	BENT	LEFT
MSKU5717290	BENT	BOTTOM
MSKU5717290	BENT	LEFT
MSKU5717290	DENT	RIGHT
MRKU9482118	BENT	BOTTOM
MRKU9482118	DENT	RIGHT
MRKU9482118	DENT	LEFT
MSKU4063548	BENT	BOTTOM
MSKU4063548	DENT	LEFT
MRKU8427440	BENT	BOTTOM
MRKU9260342	BENT	BOTTOM
MRKU9260342	DENT	LEFT
SUDU7663534	BENT	BOTTOM
SUDU7663534	DENT	LEFT
MRKU9798410	BENT	BOTTOM
MRKU9798410	DENT	LEFT
MNBU3951603	DENT	RIGHT
MNBU3951603	DENT	LEFT
TCKU2036338	DENT	RIGHT
TCKU2036338	BENT	BOTTOM




*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
TCKU2036338	DENT	LEFT
MRKU6932850	BENT	BOTTOM
MRKU6932850	DENT	RIGHT
MRKU6932850	DENT	LEFT
MNBU3094368	DENT	RIGHT
MNBU3094368	DENT	CORNER
MNBU3094368	DENT	LEFT
MNBU3094368	BENT	LEFT
SUDU6006670	BENT	RIGHT
SUDU6006670	DENT	RIGHT
SUDU6006670	DENT	LEFT
CAIU6313719	BENT	BOTTOM
CAIU6313719	BENT	RIGHT
MRKU9803096	DENT	RIGHT
MRKU9803096	BENT	BOTTOM
MRKU9803096	DENT	LEFT
MRKU9760008	BENT	BOTTOM
MRKU9760008	DENT	RIGHT
MRKU9760008	DENT	LEFT
TEMU3339689	BENT	BOTTOM
TEMU3339689	DENT	LEFT
TEMU3339689	DENT	RIGHT
HASU1379908	BENT	BOTTOM
HASU1379908	BENT	LEFT
MRKU8945049	BENT	BOTTOM
MRKU8945049	DENT	RIGHT
MRKU8945049	DENT	LEFT
MRSU0057044	BENT	BOTTOM
TRHU2015164	BENT	BOTTOM
TRHU2015164	BENT	RIGHT
TRHU2015164	DENT	LEFT
SUDU8231453	DENT	RIGHT
SUDU8231453	DENT	LEFT
MNBU9075529	DENT	RIGHT



 Signed for receipt only,
 without prejudice of liability.
 Discharged same condition as
 noted.



Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
MNBU9075529	DENT	LEFT
MRSU3763358	DENT	LEFT
MRKU0208385	DENT	LEFT
MRKU4665184	DENT	RIGHT
MNBU3161126	DENT	RIGHT
MSKU0480121	BENT	LEFT

Signed for receipt only
without prejudice of liability
Discharged same condition as
loaded.

AS NINA
1178

Without any liability accepted
Constanta South Container Terminal
Planning Department