

**DAMAGE REPORT**

Inbound carrier: MAERSK NEWPORT  
MNEW414S 414S 13-Apr-2024 16:01

| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRSU3934975 | DENT        | RIGHT           |
| MSKU8677950 | BENT        | LEFT            |
| MRSU5222898 | DENT        | RIGHT           |
| MAEU9211716 | DENT        | LEFT            |
| MRKU4303328 | BENT        | LEFT            |
| MRKU2313517 | DENT        | FLOOR           |
| MRKU3281142 | BENT        | DOORSYSTEM      |
| MRSU4436679 | BENT        | LEFT            |
| MRKU0437571 | BENT        | RIGHT           |
| MRKU0437571 | BENT        | LEFT            |
| PONU0091731 | DENT        | LEFT            |
| MRKU4156886 | DENT        | LEFT            |
| MRKU4156886 | DENT        | CORNER          |
| BEAU5746509 | CUT         | TOPROOF         |
| MRSU4147742 | DENT        | FRONT           |
| MRSU4147742 | DENT        | CORNER          |
| TGBU9358428 | DENT        | RIGHT           |
| TGBU9358428 | BENT        | LEFT            |
| MRSU6189557 | DENT        | FRONT           |
| MRKU6332011 | DENT        | LEFT            |
| GCXU5656463 | CUT         | TOPROOF         |
| MSKU0784084 | DENT        | FLOOR           |
| MRSU4110430 | DENT        | LEFT            |
| MRKU6001625 | BENT        | LEFT            |
| MRSU4156739 | BENT        | RIGHT           |
| TCKU6785437 | HOLE        | TOPROOF         |
| MRSU5177090 | BENT        | TOPROOF         |
| MRSU5177090 | BENT        | LEFT            |

*26 parts  
13-04-24  
for NEWPORT*



Without any liability accepted  
Constanta South Container Terminal  
Planning Department


| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| TEMU1357955 | DENT        | LEFT            |
| MSKU4655402 | BENT        | FRONT           |
| MSKU4655402 | DENT        | RIGHT           |
| MSKU4655402 | DENT        | LEFT            |
| MRKU4162512 | DENT        | RIGHT           |
| MRKU4162512 | BENT        | RIGHT           |
| MRKU4162512 | BENT        | LEFT            |
| MRKU4162512 | DENT        | LEFT            |
| HASU4557259 | DENT        | LEFT            |
| SUDU6782729 | DENT        | FRONT           |
| SUDU6782729 | DENT        | RIGHT           |
| SUDU6782729 | DENT        | LEFT            |
| MSKU4678861 | DENT        | RIGHT           |
| MSKU4678861 | DENT        | LEFT            |
| MSKU4725557 | IMO LABEL   | FRONT           |
| MSKU4725557 | IMO LABEL   | RIGHT           |
| MSKU4725557 | IMO LABEL   | LEFT            |
| MSKU4725557 | IMO LABEL   | BACK            |
| MRKU5112809 | BENT        | LEFT            |
| CAAU6203067 | BENT        | RIGHT           |
| CAAU6203067 | BENT        | LEFT            |
| CAAU6203067 | DENT        | CORNER          |
| MRSU3771728 | HOLE        | TOPROOF         |
| MSKU8998858 | DENT        | LEFT            |
| SEKU4443799 | BENT        | DOORSYSTEM      |
| MRSU5652029 | DENT        | LEFT            |
| MRKU2814930 | BENT        | LEFT            |
| MRKU3288717 | DENT        | LEFT            |
| MRKU0414663 | BENT        | LEFT            |
| MRKU0689634 | DENT        | LEFT            |
| MSKU1088901 | DENT        | RIGHT           |
| HASU1306455 | BENT        | BOTTOM          |
| MRKU9707493 | BENT        | BOTTOM          |
| MRKU9707493 | DENT        | LEFT            |

*260 front  
13/04/24  
for MAERSK*




| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRKU9707493 | DENT        | RIGHT           |
| MSKU5480994 | BENT        | BOTTOM          |
| MSKU5480994 | BENT        | LEFT            |
| BSIU9669000 | DENT        | RIGHT           |
| MAEU9210520 | DENT        | RIGHT           |
| MAEU9210520 | DENT        | LEFT            |
| MSKU1906994 | DENT        | CORNER          |
| MSKU1906994 | DENT        | RIGHT           |
| MRSU4056895 | BENT        | RIGHT           |
| TCKU7511873 | DENT        | RIGHT           |
| TCKU7511873 | DENT        | LEFT            |
| BSIU9021824 | DENT        | RIGHT           |
| MRKU0088485 | DENT        | RIGHT           |
| MRKU9081291 | BENT        | DOORSYSTEM      |
| TCLU5188100 | DENT        | LEFT            |
| MRKU0236176 | BENT        | RIGHT           |
| MRKU0236176 | BENT        | LEFT            |
| MRKU5001981 | DENT        | LEFT            |
| MRSU4135802 | DENT        | RIGHT           |
| MSKU9495776 | BENT        | RIGHT           |
| MRKU6434100 | DENT        | LEFT            |
| MRKU6109986 | CUT         | TOPROOF         |
| TCKU6968361 | DENT        | LEFT            |
| PONU1575052 | BENT        | RIGHT           |
| PONU1575052 | DENT        | RIGHT           |
| PONU1575052 | DENT        | LEFT            |
| MRSU6346168 | DENT        | RIGHT           |
| TRHU7127320 | DENT        | RIGHT           |
| TRHU7127320 | BENT        | RIGHT           |
| TRHU7127320 | DENT        | LEFT            |
| PONU1603447 | DENT        | RIGHT           |
| PONU1603447 | DENT        | LEFT            |
| CLHU4577266 | BENT        | LEFT            |
| CLHU4577266 | DENT        | RIGHT           |

*26/4/24  
13-04-24  
Put in front*




| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MAEU9165400 | DENT        | LEFT            |
| MRKU3491220 | DENT        | LEFT            |
| HASU4361820 | DENT        | RIGHT           |
| HASU4361820 | BENT        | LEFT            |
| MRSU5475710 | DENT        | CORNER          |
| MRSU5475710 | BENT        | LEFT            |
| MSKU9851054 | DENT        | LEFT            |
| MSKU9851054 | BENT        | RIGHT           |
| SUDU5774694 | DENT        | FRONT           |
| SUDU5774694 | BENT        | LEFT            |
| BEAU6268528 | BENT        | RIGHT           |
| TCKU7695770 | BENT        | LEFT            |
| MRKU5686350 | DENT        | RIGHT           |
| MRKU5686350 | DENT        | LEFT            |
| MRKU5686350 | BENT        | LEFT            |
| AMFU8671020 | BENT        | BOTTOM          |
| AMFU8671020 | DENT        | RIGHT           |
| AMFU8671020 | DENT        | LEFT            |
| MRKU5772227 | DENT        | LEFT            |
| CAAU6558690 | BENT        | LEFT            |
| PONU7881105 | DENT        | LEFT            |
| PONU7881105 | DENT        | RIGHT           |
| MRKU5589900 | BENT        | LEFT            |
| MRKU5719304 | BENT        | FRONT           |
| TEMU1509683 | BENT        | BOTTOM          |
| MRKU6753263 | BENT        | BOTTOM          |
| MRKU6753263 | DENT        | LEFT            |
| SUDU7999982 | BENT        | RIGHT           |
| SUDU7999982 | BENT        | BOTTOM          |
| TCLU4968689 | BENT        | LEFT            |
| MSKU6897745 | DENT        | RIGHT           |
| MSKU6897745 | DENT        | LEFT            |
| MRKU0637862 | BENT        | BOTTOM          |
| MRKU0637862 | DENT        | LEFT            |

*20 / 1304-24  
for MAERSK*




| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCLU4928109 | DENT        | RIGHT           |
| TCLU4928109 | DENT        | CORNER          |
| TEMU6699992 | DENT        | RIGHT           |
| MRKU7338014 | BENT        | LEFT            |
| CADU7036293 | BENT        | RIGHT           |
| CADU7036293 | BENT        | LEFT            |
| CADU7036293 | BENT        | DOORSYSTEM      |
| TGHU1525069 | DENT        | RIGHT           |
| TGHU1525069 | DENT        | LEFT            |
| UETU5921376 | DENT        | LEFT            |
| UETU5921376 | BENT        | BOTTOM          |
| UETU5921376 | BENT        | RIGHT           |
| MSKU4753224 | BENT        | RIGHT           |
| MSKU4638302 | DENT        | RIGHT           |
| MSKU4727420 | DENT        | FRONT           |
| MSKU9043375 | DENT        | RIGHT           |
| MSKU9043375 | DENT        | CORNER          |
| MSKU9043375 | DENT        | LEFT            |
| MSKU9043375 | BENT        | LEFT            |
| MSKU0672335 | DENT        | LEFT            |
| MSKU0672335 | DENT        | RIGHT           |
| TCNU2814871 | BENT        | LEFT            |
| SUDU8903291 | DENT        | DOORSYSTEM      |
| SUDU8903291 | CUT         | BACK            |
| GESU5783963 | HOLE        | TOPROOF         |
| CAAU6536900 | DENT        | CORNER          |
| HASU4541360 | DENT        | LEFT            |
| SUDU8776617 | DENT        | LEFT            |
| MRSU5217850 | DENT        | LEFT            |
| MMAU1376830 | BENT        | DOORSYSTEM      |
| HASU1451160 | CUT         | FRONT           |
| HASU4395688 | BENT        | RIGHT           |
| TCNU4482462 | HOLE        | TOPROOF         |
| MSKU1463406 | BENT        | LEFT            |

*ep front  
13/04-24  
for repair only*



| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRKU3515894 | BENT        | DOORSYSTEM      |
| TCKU6629753 | BENT        | RIGHT           |
| TCKU6629753 | BENT        | LEFT            |
| MRKU0118050 | DENT        | LEFT            |
| MSKU9448033 | DENT        | RIGHT           |
| MSKU9448033 | DENT        | LEFT            |
| MRSU6052142 | DENT        | FLOOR           |
| PONU1936617 | DENT        | LEFT            |
| MRKU0470369 | BENT        | BOTTOM          |
| TCNU1800019 | DENT        | LEFT            |
| TCNU1800019 | DENT        | RIGHT           |
| MRKU0115960 | DENT        | LEFT            |
| MSKU6717273 | DENT        | RIGHT           |
| MSKU6717273 | DENT        | CORNER          |
| MSKU6717273 | DENT        | LEFT            |
| PONU8257813 | DENT        | CORNER          |
| CAAU6547761 | DENT        | LEFT            |
| TCLU5793559 | BENT        | FRONT           |
| TCLU5793559 | BENT        | RIGHT           |
| TCLU5793559 | BENT        | LEFT            |
| MSKU7571943 | BENT        | RIGHT           |
| MSKU7571943 | DENT        | LEFT            |
| MSKU4641543 | DENT        | RIGHT           |
| MSKU4641543 | DENT        | LEFT            |
| TCKU1124727 | BENT        | BOTTOM          |
| TCKU1124727 | DENT        | LEFT            |
| MRKU8936303 | BENT        | BOTTOM          |
| MSKU5898808 | BENT        | BOTTOM          |
| MRKU6584163 | BENT        | BOTTOM          |
| MRKU3758209 | BENT        | RIGHT           |
| MRKU3758209 | DENT        | LEFT            |
| MSKU9008029 | DENT        | RIGHT           |
| TLLU2215658 | DENT        | LEFT            |
| TCKU1358480 | BENT        | BOTTOM          |

*26 units  
13-04-24  
for manifest*



| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCLU0710192 | BENT        | BOTTOM          |
| TCLU0710192 | BENT        | LEFT            |
| MSKU7163540 | BENT        | BOTTOM          |
| MRKU7044112 | BENT        | RIGHT           |
| MRKU7044112 | BENT        | BOTTOM          |
| CAAU5528108 | DENT        | LEFT            |
| CAIU7389426 | BENT        | LEFT            |
| MRKU5088699 | DENT        | CORNERPOST      |
| MRKU5101379 | BENT        | FRONT           |

*26 front  
for m26/r only  
B-24-24*



Without any liability accepted  
Constanta South Container Terminal  
Planning Department

*[Handwritten signature]*