

DAMAGE REPORT

Inbound carrier: MED STAR

MEDS01 01

03-May-2024 12:49

Container	Damage type	Damage location
TCKU6928883	DENT	RIGHT
MRSU4622312	BENT	LEFT
MAEU4178852	CUT	TARPAULIN
SUDU8797097	BENT	LEFT
MSKU0947812	DENT	LEFT
MSKU0947812	BENT	FRONT
MRKU3582969	DENT	RIGHT
MRKU3582969	DENT	LEFT
AMFU8735063	DENT	RIGHT
MRSU0307673	BENT	FRONT
MRSU0307673	BENT	RIGHT
MRKU3930616	BENT	RIGHT
MRKU5713287	BENT	LEFT
MRKU5713287	DENT	FLOOR
TCLU3027718	BENT	RIGHT
MRSU6541436	HOLE	TOPROOF
MRKU4429912	BENT	LEFT
MNBU9122750	HOLE	TOPROOF
MNBU4268989	CUT	RIGHT
MRKU3984058	DENT	RIGHT
MRKU3984058	BENT	FRONT
TCNU2888806	DENT	LEFT
MAEU3416909	SCRATCHED	LEFT
MSKU1885818	DENT	LEFT
MRKU3236117	DENT	RIGHT
TCKU6611081	DENT	RIGHT
HASU5117444	DENT	LEFT
MSKU9756308	DENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department



Container	Damage type	Damage location
MSKU9756308	DENT	RIGHT
MRSU4608607	BENT	RIGHT
MRKU4104917	DENT	LEFT
SUDU8591001	DENT	RIGHT
TRHU4253120	BENT	RIGHT
TRHU4253120	BENT	LEFT
PONU8238686	BENT	LEFT
MRSU4933802	DENT	LEFT
MRKU2271005	TORN	DOORSYSTEM
MRKU7126078	CUT	FRONT
MSKU1294604	BROKEN	DOORSYSTEM
HASU5158891	DENT	LEFT
HASU4322763	BENT	RIGHT
MRKU0141430	DENT	LEFT
MRKU3977336	BENT	RIGHT
MRKU8209161	BENT	RIGHT
MRKU8209161	BENT	LEFT
MRKU3786978	BENT	RIGHT
SUDU7352445	BENT	LEFT
TRLU7617239	BENT	RIGHT
TCLU3238140	DENT	RIGHT
MSKU3511910	DENT	LEFT
MRKU5761789	DENT	RIGHT
MRSU4342899	BENT	LEFT
MSKU3953362	DENT	FRONT
TCLU6987203	BENT	RIGHT
TCLU6987203	BENT	LEFT
TCKU1196706	DENT	LEFT
MRKU8446604	BENT	RIGHT
MRKU8446604	BENT	LEFT
MRKU8446604	DENT	CORNERPOST
MRKU4532387	BENT	RIGHT
MRKU9587422	BENT	RIGHT
MRKU9587422	BENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU9966323	BENT	LEFT
MRKU7488246	BENT	RIGHT
MRKU7488246	BENT	LEFT
MRKU9988976	BENT	RIGHT
MRKU9988976	BENT	LEFT
MRKU6251727	BENT	LEFT
MRKU2789904	BENT	RIGHT
MSKU1703580	DENT	RIGHT
MSKU0778712	BENT	RIGHT
MRKU2592284	DENT	RIGHT
MAEU4172242	CUT	TARPAULIN
MSKU9347629	BENT	LEFT
MRSU5573589	DENT	LEFT
MRKU3246516	DENT	LEFT
MRKU2595534	DENT	RIGHT
TEMU7890811	DENT	LEFT
MRKU9759429	DENT	RIGHT
MRKU9759429	DENT	RIGHT
TCKU6848303	DENT	LEFT
MRKU9957738	BENT	RIGHT
HASU1428767	BENT	LEFT
MRKU4732209	DENT	LEFT
MRKU9783195	DENT	LEFT
MSKU8824141	DENT	RIGHT
SUDU8224562	DENT	LEFT
TCKU6723862	DENT	LEFT
TCKU6723862	DENT	RIGHT
TGHU6711826	BENT	FRONT
TGHU6711826	BENT	RIGHT
TGHU6711826	DENT	LEFT
TGHU6711826	DENT	CORNERPOST
MSKU0752868	BENT	LEFT
MSKU0752868	BENT	RIGHT
HASU1134510	BENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
HASU1134510	BENT	LEFT
TCKU7993266	CUT	BACK
MSKU0185173	BENT	LEFT
MRKU6396187	CUT	BACK
HASU4189563	DENT	DOOR
HASU4189563	DENT	LEFT
MRKU4739081	BENT	RIGHT
MSKU7587235	BENT	CORNER
TRHU6089334	BENT	RIGHT
MRSU3018252	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

