

DAMAGE REPORT

Inbound carrier: ANNIE B

ANNB629S 629S

20-Jul-2026 05:28

Container	Damage type	Damage location
BEAU5683062	DENT	LEFT
BEAU5920333	CUT	FRONT
BMOU2708290	DENT	LEFT
BMOU2708290	CUT	RIGHT
BMOU2708290	DENT	FRONT
CAAU2217587	DENT	LEFT
CAAU5342140	DENT	CORNERPOST
CAAU6429711	DENT	RIGHT
CAAU6429711	DENT	LEFT
CAAU6459418	DENT	RIGHT
CAAU6468770	DENT	RIGHT
CAAU6528205	SCRATCHED	RIGHT
CAAU6528205	SCRATCHED	LEFT
CAAU6528205	DENT	CORNERPOST
CAAU6614350	BENT	RIGHT
CAAU7177928	DENT	LEFT
CAAU7177928	DENT	FRONT
CAAU7181070	DENT	RIGHT
CAAU7207766	BENT	LEFT
CAAU8480380	DENT	RIGHT
CAAU8642454	BENT	RIGHT
CAAU9220670	DENT	LEFT
CAAU9595418	DENT	RIGHT
CAAU9595418	BENT	RIGHT
CAIU9391612	DENT	LEFT
CAIU9391612	BENT	LEFT
CAIU9391612	CUT	RIGHT
CAIU9391612	BENT	RIGHT

FOR RECEIPT ONLY
WITHOUT PREJUDICE

M. V. ANNIE B

CHIEF OFFICER

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
CAIU9391612	DENT	RIGHT
CAIU9391612	DENT	CORNERPOST
CAXU9986680	DENT	RIGHT
CIPU5059673	DENT	RIGHT
CIPU5086771	BENT	FRONT
CIPU5123941	DENT	RIGHT
CIPU5247602	BENT	LEFT
CNIU2463277	DENT	CORNERPOST
DFSU6092461	DENT	CORNERPOST
FCIU9085375	BENT	RIGHT
FCIU9085375	BENT	LEFT
FFAU2281173	BENT	RIGHT
FFAU2281173	DENT	LEFT
FFAU2281173	BENT	LEFT
FFAU2281173	DENT	RIGHT
FFAU2343172	DENT	LEFT
FFAU2343172	BENT	RIGHT
FFAU6632928	DENT	LEFT
FFAU7105829	DENT	LEFT
GAOU7320780	SCRATCHED	LEFT
GAOU7320780	DENT	LEFT
GAOU7344436	BENT	RIGHT
GAOU7344436	BENT	LEFT
GAOU7347184	BENT	RIGHT
GATU8777969	RUSTED	LEFT
GATU8777969	DENT	LEFT
GATU8777969	RUSTED	RIGHT
GATU8777969	DENT	CORNERPOST
GCXU5587070	SCRATCHED	RIGHT
GCXU5587070	SCRATCHED	LEFT
GCXU5681050	BENT	FLOOR
GCXU5703082	BENT	LEFT
GCXU5716520	BENT	RIGHT
GCXU5716520	BENT	LEFT

Without any liability accepted
Denscon's South Container Terminal
Planning Department

M.V. ANNIE B
Arac
CHIEF OFFICER

Page 2 of 25
FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
GCXU5722631	DENT	LEFT
GCXU5794082	DENT	RIGHT
GCXU5794082	DENT	LEFT
GCXU6296947	DENT	LEFT
GCXU6393510	BENT	FLOOR
GLDU5604133	DENT	FRONT
GLDU5604133	DENT	CORNERPOST
HASU1343103	BENT	LEFT
HASU1343103	DENT	CORNERPOST
HASU1383282	BENT	FRONT
HASU1545357	DENT	RIGHT
HASU1545357	BENT	FRONT
HASU1545357	DENT	LEFT
HASU1545357	CUT	RIGHT
HASU1567654	DENT	RIGHT
HASU1567654	DENT	DOORSYSTEM
HASU1567654	DENT	FRONT
HASU1567654	BENT	BOTTOM
HASU1567654	CUT	LEFT
HASU1567654	BENT	LEFT
HASU1567654	DENT	LEFT
HASU4040097	DENT	LEFT
HASU4107950	BENT	FRONT
HASU4117780	BENT	RIGHT
HASU4386686	BENT	LEFT
HASU4386834	RUSTED	FRONT
HASU4386834	SCRATCHED	LEFT
HASU4386834	DENT	CORNERPOST
HASU4476542	BULGED	LEFT
HASU4476542	DENT	CORNERPOST
HASU4476542	BENT	RIGHT
HASU4481934	BENT	FRONT
HASU4481934	DENT	LEFT
HASU4481934	BENT	LEFT

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B
Heer
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
HASU4481934	BENT	RIGHT
HASU4481934	DENT	RIGHT
HASU4481934	DENT	DOORSYSTEM
HASU4481934	DENT	FRONT
HASU4553700	CUT	FRONT
HASU4594993	BENT	RIGHT
HASU4594993	DENT	FRONT
HASU4594993	DENT	LEFT
HASU4594993	BENT	LEFT
HASU4594993	DENT	RIGHT
HASU4627612	DENT	CORNERPOST
HASU4631021	CUT	RIGHT
HASU4703841	BENT	RIGHT
HASU4835107	BENT	FRONT
HASU4947410	BENT	LEFT
HASU4957358	BENT	LEFT
HASU4973370	BENT	FRONT
HASU4973370	DENT	LEFT
HASU4973370	BENT	RIGHT
HASU4975201	BENT	FRONT
HASU5013239	BENT	LEFT
HASU5061983	DENT	LEFT
HASU5061983	BENT	LEFT
HASU5061983	DENT	RIGHT
HASU5061983	BENT	RIGHT
HASU5061983	DENT	FRONT
HASU5061983	BENT	FRONT
HASU5171635	SCRATCHED	LEFT
HASU5171635	DENT	RIGHT
HASU5192520	DENT	RIGHT
MAEU4186971	CUT	TARPAULIN
MAEU4188110	CUT	TARPAULIN
MAEU4211626	CUT	TARPAULIN
MAEU4702954	CUT	TARPAULIN

M. V. ANNIE B

CHIEF OFFICER

Container	Damage type	Damage location
MAEU9195024	RUSTED	FRONT
MAEU9201908	DENT	RIGHT
MAEU9202838	DENT	LEFT
MAGU2504915	DENT	LEFT
MAGU2504915	DENT	RIGHT
MAGU2504915	BENT	RIGHT
MAGU2504915	DENT	FRONT
MAGU5623944	DENT	LEFT
MAGU5623944	DENT	RIGHT
MIEU2018975	DENT	CORNERPOST
MIEU3005611	DENT	RIGHT
MIEU3006860	DENT	RIGHT
MIEU3063330	DENT	LEFT
MMAU1464762	BENT	DOORSYSTEM
MRKU0360700	DENT	CORNERPOST
MRKU0446697	DENT	LEFT
MRKU0748207	DENT	CORNERPOST
MRKU0866339	DENT	FRONT
MRKU0866339	DENT	LEFT
MRKU0866339	BENT	LEFT
MRKU0866339	DENT	RIGHT
MRKU0866339	BENT	RIGHT
MRKU0939498	DENT	CORNERPOST
MRKU0987135	DENT	RIGHT
MRKU0987135	DENT	LEFT
MRKU0987135	BENT	RIGHT
MRKU0987135	DENT	CORNERPOST
MRKU1019853	DENT	FRONT
MRKU1019853	DENT	LEFT
MRKU1019853	DENT	RIGHT
MRKU1019853	BENT	RIGHT
MRKU2049662	BENT	LEFT
MRKU2096200	RUSTED	CORNERPOST
MRKU2096200	DENT	CORNERPOST

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B

CHIEF OFFICER

Page 5 of 25

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU2130394	DENT	CORNERPOST
MRKU2130394	SCRATCHED	RIGHT
MRKU2208569	DENT	FRONT
MRKU2208569	DENT	LEFT
MRKU2208569	DENT	RIGHT
MRKU2208569	BENT	RIGHT
MRKU2348468	DENT	CORNERPOST
MRKU2437288	DENT	CORNERPOST
MRKU2437288	DENT	LEFT
MRKU2437288	BENT	LEFT
MRKU2437288	DENT	RIGHT
MRKU2437288	BENT	RIGHT
MRKU2451497	DENT	LEFT
MRKU2451497	DENT	RIGHT
MRKU2529580	RUSTED	RIGHT
MRKU2529580	BENT	LEFT
MRKU2540207	SCRATCHED	LEFT
MRKU2540207	DENT	RIGHT
MRKU2551639	DENT	LEFT
MRKU2553288	SCRATCHED	RIGHT
MRKU2553288	RUSTED	FRONT
MRKU2562124	BENT	CORNER
MRKU2562124	BENT	CORNERPOST
MRKU2612523	BENT	RIGHT
MRKU2612523	DENT	RIGHT
MRKU2612523	BENT	LEFT
MRKU2612523	DENT	LEFT
MRKU2612523	DENT	FRONT
MRKU2695209	BENT	FLOOR
MRKU2767103	DENT	CORNERPOST
MRKU2767103	RUSTED	FRONT
MRKU2800813	BENT	LEFT
MRKU2887984	RUSTED	FRONT
MRKU3085561	BENT	RIGHT

Without any liability accepted
Consolidated Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU3085561	DENT	LEFT
MRKU3085561	BENT	LEFT
MRKU3085561	DENT	CORNERPOST
MRKU3085561	DENT	RIGHT
MRKU3108944	BENT	RIGHT
MRKU3108944	BENT	LEFT
MRKU3108944	DENT	RIGHT
MRKU3144685	BENT	LEFT
MRKU3240307	DENT	RIGHT
MRKU3240307	DENT	LEFT
MRKU3302029	SCRATCHED	LEFT
MRKU3302029	DENT	RIGHT
MRKU3404587	DENT	CORNERPOST
MRKU3440922	BENT	RIGHT
MRKU3440922	BENT	LEFT
MRKU3464610	DENT	FRONT
MRKU3464610	DENT	LEFT
MRKU3464610	BENT	LEFT
MRKU3464610	DENT	RIGHT
MRKU3464610	BENT	RIGHT
MRKU3502665	DENT	RIGHT
MRKU3502665	DENT	LEFT
MRKU3569951	DENT	LEFT
MRKU3569951	DENT	RIGHT
MRKU3587240	DENT	LEFT
MRKU3648840	DENT	LEFT
MRKU3705997	DENT	CORNERPOST
MRKU3705997	DENT	LEFT
MRKU3705997	BENT	LEFT
MRKU3705997	DENT	RIGHT
MRKU3705997	BENT	RIGHT
MRKU3705997	DENT	FRONT
MRKU3793597	BENT	FLOOR
MRKU3830392	DENT	FRONT

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B
Area
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU3830392	DENT	LEFT
MRKU3830392	BENT	LEFT
MRKU3830392	BENT	RIGHT
MRKU3830392	DENT	RIGHT
MRKU3914169	DENT	CORNERPOST
MRKU3914169	SCRATCHED	LEFT
MRKU3914169	SCRATCHED	RIGHT
MRKU3930724	DENT	RIGHT
MRKU3964365	DENT	LEFT
MRKU3968381	DENT	RIGHT
MRKU3974656	SCRATCHED	RIGHT
MRKU3974656	DENT	CORNERPOST
MRKU3974656	SCRATCHED	LEFT
MRKU4083711	BENT	LEFT
MRKU4083711	DENT	RIGHT
MRKU4083711	BENT	TOPROOF
MRKU4123645	DENT	RIGHT
MRKU4123645	CUT	FRONT
MRKU4144571	BENT	LEFT
MRKU4144571	DENT	CORNERPOST
MRKU4144571	DENT	RIGHT
MRKU4144571	DENT	LEFT
MRKU4387627	DENT	RIGHT
MRKU4430235	DENT	RIGHT
MRKU4436948	DENT	CORNERPOST
MRKU4492643	DENT	RIGHT
MRKU4575970	DENT	RIGHT
MRKU4575970	BENT	LEFT
MRKU4585638	BENT	LEFT
MRKU4597454	BENT	RIGHT
MRKU4597454	DENT	CORNERPOST
MRKU4597454	DENT	FRONT
MRKU4597454	DENT	LEFT
MRKU4597454	BENT	LEFT

Without any liability accepted
Consistent South Container Terminal
Piercing Department

M. V. ANNIE B
M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU4597454	DENT	RIGHT
MRKU4639502	RUSTED	RIGHT
MRKU4686588	BENT	LEFT
MRKU4692488	SCRATCHED	RIGHT
MRKU4692488	SCRATCHED	LEFT
MRKU4711063	SCRATCHED	RIGHT
MRKU4711063	SCRATCHED	LEFT
MRKU4823802	DENT	CORNER
MRKU4990190	BENT	RIGHT
MRKU4990190	DENT	RIGHT
MRKU4990190	BENT	LEFT
MRKU4990190	DENT	LEFT
MRKU4990190	BENT	FRONT
MRKU5013555	BENT	RIGHT
MRKU5013555	DENT	RIGHT
MRKU5014382	DENT	CORNERPOST
MRKU5218690	SCRATCHED	LEFT
MRKU5218690	RUSTED	RIGHT
MRKU5341282	BENT	RIGHT
MRKU5390266	SCRATCHED	RIGHT
MRKU5449235	BENT	LEFT
MRKU5450262	DENT	RIGHT
MRKU5463629	RUSTED	CORNERPOST
MRKU5535539	DENT	LEFT
MRKU5573246	DENT	RIGHT
MRKU5591281	DENT	LEFT
MRKU5912545	BENT	RIGHT
MRKU5912545	DENT	CORNERPOST
MRKU5912545	DENT	LEFT
MRKU5915930	HOLE	TOPROOF
MRKU5936070	DENT	RIGHT
MRKU6013950	SCRATCHED	LEFT
MRKU6021787	DENT	CORNERPOST
MRKU6035409	DENT	RIGHT

Without any liability accepted
Consolidated South Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU6166219	BENT	RIGHT
MRKU6166219	DENT	LEFT
MRKU6166219	BENT	LEFT
MRKU6166219	DENT	RIGHT
MRKU6199439	DENT	RIGHT
MRKU6199439	DENT	LEFT
MRKU6210815	DENT	LEFT
MRKU6241354	DENT	RIGHT
MRKU6254789	BENT	FRONT
MRKU6254789	DENT	LEFT
MRKU6254789	DENT	DOORSYSTEM
MRKU6254789	BENT	RIGHT
MRKU6254789	DENT	RIGHT
MRKU6395025	BENT	RIGHT
MRKU6410794	BENT	RIGHT
MRKU6410794	BENT	LEFT
MRKU6414193	BENT	LEFT
MRKU6414193	BENT	RIGHT
MRKU6542424	BENT	LEFT
MRKU6542424	BENT	FRONT
MRKU6542424	BENT	RIGHT
MRKU6542424	DENT	CORNER
MRKU6542424	DENT	DOORSYSTEM
MRKU6542424	DENT	BACK
MRKU6542424	DENT	LEFT
MRKU6583465	DENT	FRONT
MRKU6583465	BENT	LEFT
MRKU6583465	BENT	RIGHT
MRKU6583465	DENT	CORNERPOST
MRKU6647940	DENT	RIGHT
MRKU6647940	DENT	LEFT
MRKU6672726	BENT	RIGHT
MRKU6672726	BENT	LEFT
MRKU6943598	DENT	LEFT

Container	Damage type	Damage location
MRKU6943598	DENT	RIGHT
MRKU6943598	BENT	RIGHT
MRKU6943598	BENT	LEFT
MRKU7094263	BENT	FRONT
MRKU7094263	DENT	RIGHT
MRKU7133288	SCRATCHED	FRONT
MRKU7186272	BENT	BOTTOM
MRKU7191854	DENT	RIGHT
MRKU7267672	DENT	FRONT
MRKU7267672	BENT	RIGHT
MRKU7529495	DENT	RIGHT
MRKU7529495	BENT	LEFT
MRKU7575130	DENT	LEFT
MRKU7575130	BENT	FRONT
MRKU7575130	DENT	RIGHT
MRKU7641340	DENT	RIGHT
MRKU7660606	DENT	LEFT
MRKU7660606	DENT	FRONT
MRKU7660606	DENT	RIGHT
MRKU7739676	DENT	FRONT
MRKU7739676	DENT	CORNERPOST
MRKU7739676	DENT	RIGHT
MRKU7739676	BENT	RIGHT
MRKU7861956	DENT	FRONT
MRKU7861956	DENT	LEFT
MRKU7861956	BENT	LEFT
MRKU7861956	BENT	RIGHT
MRKU8137694	SCRATCHED	RIGHT
MRKU8137694	BENT	BOTTOM
MRKU8138638	DENT	LEFT
MRKU8181573	BENT	LEFT
MRKU8260380	DENT	FRONT
MRKU8260380	DENT	LEFT
MRKU8260380	DENT	RIGHT

Container	Damage type	Damage location
MRKU8280180	CUT	BOTTOM
MRKU8380322	BENT	BOTTOM
MRKU8430790	DENT	LEFT
MRKU8430790	BENT	FRONT
MRKU8430790	BENT	RIGHT
MRKU8430790	DENT	RIGHT
MRKU8481884	DENT	LEFT
MRKU8481884	DENT	RIGHT
MRKU8481884	DENT	FRONT
MRKU8483980	BENT	BOTTOM
MRKU8508049	DENT	LEFT
MRKU8508049	DENT	RIGHT
MRKU8508049	DENT	FRONT
MRKU8508049	BENT	FRONT
MRKU8541659	DENT	FRONT
MRKU8541659	DENT	CORNERPOST
MRKU8541659	DENT	LEFT
MRKU8541659	DENT	RIGHT
MRKU8583612	DENT	DOORSYSTEM
MRKU8583612	DENT	RIGHT
MRKU8583612	DENT	FRONT
MRKU8583612	DENT	LEFT
MRKU8637880	DENT	FRONT
MRKU8637880	DENT	LEFT
MRKU8637880	DENT	RIGHT
MRKU8674883	DENT	RIGHT
MRKU8674883	DENT	CORNERPOST
MRKU8674883	SCRATCHED	LEFT
MRKU8674883	SCRATCHED	FRONT
MRKU8797975	DENT	FRONT
MRKU8797975	DENT	LEFT
MRKU8797975	BENT	LEFT
MRKU8797975	DENT	RIGHT
MRKU8797975	BENT	RIGHT

Without any liability accepted
Consolidated South Container Terminal
Planning Department

M. V. ANNIE B
AKOO
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRKU9109193	DENT	RIGHT
MRKU9109193	DENT	LEFT
MRKU9259547	DENT	LEFT
MRKU9271162	DENT	FRONT
MRKU9271162	DENT	LEFT
MRKU9271162	BENT	RIGHT
MRKU9310232	DENT	LEFT
MRKU9310232	DENT	RIGHT
MRKU9431661	BENT	LEFT
MRKU9431661	DENT	RIGHT
MRKU9431661	BENT	RIGHT
MRKU9431661	DENT	LEFT
MRKU9538840	BENT	LEFT
MRKU9538840	BENT	FRONT
MRKU9538840	DENT	RIGHT
MRKU9538840	BENT	RIGHT
MRKU9538840	DENT	LEFT
MRKU9561048	BENT	FRONT
MRKU9561048	BENT	LEFT
MRKU9561048	DENT	RIGHT
MRKU9561048	BENT	RIGHT
MRKU9561048	DENT	FRONT
MRKU9581358	DENT	LEFT
MRKU9581358	DENT	CORNERPOST
MRKU9581358	DENT	FRONT
MRKU9581358	DENT	RIGHT
MRKU9663121	DENT	LEFT
MRKU9663121	BENT	LEFT
MRKU9663121	DENT	RIGHT
MRKU9663121	BENT	RIGHT
MRKU9663121	DENT	FRONT
MRKU9663121	BENT	FRONT
MRKU9663121	DENT	FRONT
MRKU9851469	CUT	LEFT

Container	Damage type	Damage location
MRKU9851469	DENT	LEFT
MRKU9851469	DENT	RIGHT
MRKU9851469	BENT	RIGHT
MRKU9851469	DENT	FRONT
MRKU9851469	DENT	CORNERPOST
MRSU0019379	BENT	RIGHT
MRSU0160685	BENT	RIGHT
MRSU0160685	DENT	RIGHT
MRSU0160685	BENT	RIGHT
MRSU0160685	DENT	FRONT
MRSU0160685	DENT	RIGHT
MRSU0172726	SCRATCHED	LEFT
MRSU0172726	DENT	CORNERPOST
MRSU0172726	DIRTY	RIGHT
MRSU0172726	SCRATCHED	RIGHT
MRSU0237719	BENT	LEFT
MRSU0237719	DENT	RIGHT
MRSU0237719	BENT	RIGHT
MRSU0237719	DENT	LEFT
MRSU1082273	DENT	BACK
MRSU2064588	BENT	DOORSYSTEM
MRSU3134165	DENT	RIGHT
MRSU3299226	DENT	RIGHT
MRSU3299226	DENT	CORNERPOST
MRSU3312457	DENT	RIGHT
MRSU3446292	DENT	LEFT
MRSU3459540	BENT	RIGHT
MRSU3459540	BENT	LEFT
MRSU3459540	DENT	LEFT
MRSU3459540	DENT	RIGHT
MRSU3569851	DENT	LEFT
MRSU3569851	BENT	LEFT
MRSU3569851	DENT	BACK
MRSU3569851	DENT	RIGHT

Without any liability accepted
Gensler's South Container Terminal
Planning Department

M. V. ANNIE B
A. V. C.
CHIEF OFFICER

Page 14 of 25
FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRSU3569851	BENT	RIGHT
MRSU3569851	CUT	RIGHT
MRSU3569851	DENT	FRONT
MRSU3569851	DENT	CORNERPOST
MRSU3613208	RUSTED	LEFT
MRSU3613208	DENT	CORNERPOST
MRSU3646006	DENT	CORNERPOST
MRSU3757587	BENT	RIGHT
MRSU3757587	DENT	FRONT
MRSU3757587	DENT	LEFT
MRSU3757587	BENT	LEFT
MRSU3757587	DENT	RIGHT
MRSU3981597	DENT	FRONT
MRSU3981597	DENT	CORNERPOST
MRSU3981597	BENT	LEFT
MRSU3981597	DENT	RIGHT
MRSU4049094	DENT	LEFT
MRSU4078322	DENT	LEFT
MRSU4078322	DENT	RIGHT
MRSU4078322	BENT	RIGHT
MRSU4078322	DENT	CORNERPOST
MRSU4078322	DENT	FRONT
MRSU4078322	BENT	FRONT
MRSU4135675	DENT	LEFT
MRSU4154757	DENT	CORNERPOST
MRSU4303819	BENT	RIGHT
MRSU4325865	DENT	RIGHT
MRSU4428457	SCRATCHED	LEFT
MRSU4431487	DENT	CORNERPOST
MRSU4527280	DENT	CORNERPOST
MRSU4772919	BENT	LEFT
MRSU4799020	BENT	LEFT
MRSU4799020	BENT	RIGHT
MRSU4986612	DENT	RIGHT

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

Container	Damage type	Damage location
MRSU4993226	BENT	LEFT
MRSU4993226	DENT	RIGHT
MRSU5215862	SCRATCHED	RIGHT
MRSU5217741	DENT	RIGHT
MRSU5321205	BENT	FRONT
MRSU5321205	BENT	LEFT
MRSU5321205	BENT	RIGHT
MRSU5321205	DENT	FRONT
MRSU5345526	BENT	FRONT
MRSU5345526	DENT	CORNERPOST
MRSU5462625	BENT	RIGHT
MRSU5462625	BENT	LEFT
MRSU5490859	DENT	RIGHT
MRSU5517604	DENT	RIGHT
MRSU5522093	DENT	CORNERPOST
MRSU5597805	DENT	CORNERPOST
MRSU5618678	BENT	LEFT
MRSU5855010	DENT	FRONT
MRSU5855010	DENT	LEFT
MRSU5855010	DENT	RIGHT
MRSU6040096	DENT	RIGHT
MRSU6040096	DENT	LEFT
MRSU6058006	DENT	RIGHT
MRSU6182655	DENT	CORNERPOST
MRSU6183625	DENT	CORNERPOST
MRSU6183625	BENT	RIGHT
MRSU6463436	BENT	RIGHT
MRSU6463436	DIRTY	LEFT
MRSU6463436	BENT	LEFT
MRSU6902879	BENT	LEFT
MRSU6976629	DENT	FRONT
MRSU7044537	BENT	RIGHT
MRSU7044537	BENT	LEFT
MRSU7228391	DENT	LEFT

Without any liability accepted
Consentia South Container Terminal
Piercing Department

M. V. ANNIE B
AKW
CHIEF OFFICER

Page 16 of 25
FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MRSU7345905	DENT	RIGHT
MRSU7403827	BENT	LEFT
MRSU7494581	BENT	RIGHT
MRSU7569593	DENT	CORNERPOST
MRSU7606064	BENT	LEFT
MRSU7606064	BENT	RIGHT
MRSU8476941	DENT	RIGHT
MRSU8613582	DENT	RIGHT
MRSU8791579	DENT	RIGHT
MSKU0351736	BENT	RIGHT
MSKU0428289	BENT	RIGHT
MSKU0539451	DENT	RIGHT
MSKU0657140	DENT	CORNERPOST
MSKU0657140	RUSTED	FRONT
MSKU0718225	SCRATCHED	RIGHT
MSKU0718225	DENT	CORNERPOST
MSKU1018479	DENT	CORNERPOST
MSKU1093030	DENT	RIGHT
MSKU1093030	DENT	LEFT
MSKU1100864	DENT	CORNERPOST
MSKU1100864	BENT	LEFT
MSKU1100864	DENT	RIGHT
MSKU1175591	SCRATCHED	FRONT
MSKU1175591	SCRATCHED	LEFT
MSKU1175591	SCRATCHED	RIGHT
MSKU1175591	DENT	CORNERPOST
MSKU1268570	DENT	RIGHT
MSKU1460937	DENT	CORNERPOST
MSKU1555903	DENT	CORNERPOST
MSKU1621780	DENT	LEFT
MSKU1624650	SCRATCHED	LEFT
MSKU1624650	BENT	RIGHT
MSKU1624650	RUSTED	FRONT
MSKU1668670	DENT	CORNERPOST

With out any accepted
Consistent South Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MSKU1683798	BENT	RIGHT
MSKU1792905	DENT	LEFT
MSKU1805751	SCRATCHED	LEFT
MSKU1924637	BENT	FRONT
MSKU1924637	DENT	CORNERPOST
MSKU3617856	DENT	FRONT
MSKU3617856	DENT	LEFT
MSKU3617856	DENT	RIGHT
MSKU3682276	DENT	CORNERPOST
MSKU3682276	BENT	FRONT
MSKU3911238	DENT	LEFT
MSKU3911238	BENT	RIGHT
MSKU4764722	DENT	RIGHT
MSKU4797201	RUSTED	FRONT
MSKU4806514	BENT	FRONT
MSKU4829741	HOLE	TOPROOF
MSKU5267000	BENT	FRONT
MSKU5267000	DENT	FRONT
MSKU5267000	BENT	RIGHT
MSKU5267000	DENT	RIGHT
MSKU5267000	BENT	LEFT
MSKU5494874	DENT	CORNERPOST
MSKU5653322	BENT	LEFT
MSKU5713355	BENT	LEFT
MSKU5713355	DENT	RIGHT
MSKU5713355	BENT	RIGHT
MSKU5713355	HOLE	FRONT
MSKU5713355	CUT	FRONT
MSKU5713355	DENT	FRONT
MSKU5713355	CUT	LEFT
MSKU5713355	DENT	LEFT
MSKU5825885	DENT	RIGHT
MSKU5825885	DENT	LEFT
MSKU5848849	DENT	RIGHT

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B
A. Keco
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
MSKU5848849	BENT	LEFT
MSKU5848849	DENT	LEFT
MSKU5848849	DENT	FRONT
MSKU5983807	DENT	LEFT
MSKU7598760	BENT	FRONT
MSKU7598760	DENT	FRONT
MSKU7598760	BENT	RIGHT
MSKU7598760	DENT	LEFT
MSKU7660510	DENT	RIGHT
MSKU7829724	DENT	LEFT
MSKU7889805	DENT	FRONT
MSKU7889805	DENT	LEFT
MSKU7889805	BENT	LEFT
MSKU7889805	DENT	RIGHT
MSKU7889805	BENT	RIGHT
MSKU9701408	SCRATCHED	LEFT
MSKU9797570	DENT	LEFT
MSKU9797570	BENT	LEFT
MSKU9797570	DENT	RIGHT
MSKU9797570	BENT	RIGHT
MSKU9797570	BENT	FRONT
MSKU9797570	RUSTED	FRONT
MSKU9838659	BENT	RIGHT
MVIU0030269	CUT	FRONT
SEGU4238315	BENT	LEFT
SEGU4268710	DENT	RIGHT
SEGU4268710	DENT	CORNERPOST
SEKU4691814	DENT	LEFT
SEKU4691814	DENT	RIGHT
SEKU4695949	SCRATCHED	LEFT
SEKU4722582	DENT	LEFT
SEKU6967408	IMO LABEL	LEFT
SEKU6967408	IMO LABEL	RIGHT
SEKU6978260	SCRATCHED	RIGHT

Without any liability accepted
Consinta South Container Terminal
Planning Department

M. Y. ANNIE B
H Kew
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
SELU4065905	DENT	LEFT
SUDU1491443	BENT	FRONT
SUDU1491443	SCRATCHED	LEFT
SUDU1491443	SCRATCHED	RIGHT
SUDU6631002	DENT	CORNERPOST
SUDU6741627	DENT	FRONT
SUDU6741627	DENT	LEFT
SUDU6741627	BENT	LEFT
SUDU6741627	DENT	RIGHT
SUDU6741627	BENT	RIGHT
SUDU6913290	BENT	BACK
SUDU7473935	DENT	FRONT
SUDU7473935	DENT	RIGHT
SUDU7473935	DENT	LEFT
SUDU7862900	RUSTED	CORNERPOST
SUDU7862900	DENT	CORNERPOST
SUDU7952291	DENT	RIGHT
SUDU8527044	DENT	CORNERPOST
SUDU8667489	DENT	CORNERPOST
SUDU8667489	DENT	LEFT
SUDU8667489	DENT	RIGHT
SUDU8667489	BENT	RIGHT
SUDU8667489	DENT	FRONT
SUDU8667489	BENT	FRONT
SUDU8711391	BENT	LEFT
SUDU8831041	BENT	RIGHT
SUDU8831041	DENT	FRONT
SUDU8831041	BENT	LEFT
SUDU8891760	BENT	LEFT
TCKU1072921	CUT	RIGHT
TCKU1072921	DENT	FRONT
TCKU1072921	BENT	FRONT
TCKU1072921	BENT	RIGHT
TCKU1072921	DENT	RIGHT

Without any liability accepted
Consistent South Container Terminal
Planning Department

M. V. ANNIE B
A. K. C.
CHIEF OFFICER

Page 20 of 25
FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
TCKU1072921	DENT	LEFT
TCKU1273680	BENT	RIGHT
TCKU3977879	DENT	LEFT
TCKU3977879	BENT	RIGHT
TCKU3977879	DENT	FRONT
TCKU6129470	SCRATCHED	RIGHT
TCKU6129470	SCRATCHED	LEFT
TCKU6491849	SCRATCHED	LEFT
TCKU6521120	BENT	RIGHT
TCKU6529040	DENT	LEFT
TCKU6529040	BENT	RIGHT
TCKU6606228	DENT	DOORSYSTEM
TCKU6773842	DENT	FRONT
TCKU6773842	DENT	CORNERPOST
TCKU6882123	SCRATCHED	RIGHT
TCKU7300382	BENT	RIGHT
TCKU7300382	DENT	LEFT
TCKU7300382	BENT	LEFT
TCKU7300382	DENT	RIGHT
TCKU7447943	SCRATCHED	RIGHT
TCKU7447943	SCRATCHED	LEFT
TCKU7456225	BENT	RIGHT
TCKU7456225	BENT	LEFT
TCKU7457411	DENT	LEFT
TCKU7638111	DENT	CORNERPOST
TCKU7715434	DENT	LEFT
TCKU7715434	DENT	RIGHT
TCKU7748280	BENT	RIGHT
TCKU7762966	DENT	CORNERPOST
TCLU3652079	BENT	RIGHT
TCLU3652079	DENT	LEFT
TCLU3652079	DENT	FRONT
TCLU5344250	DENT	CORNERPOST
TCLU5423641	BENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
TCLU5423641	BENT	RIGHT
TCLU5424144	SCRATCHED	LEFT
TCLU8044003	DENT	LEFT
TCLU9248228	DENT	CORNERPOST
TCNU1474627	BENT	LEFT
TCNU1474627	BENT	RIGHT
TCNU1813206	DENT	LEFT
TCNU1930711	DENT	LEFT
TCNU2207369	DENT	RIGHT
TCNU2822537	SCRATCHED	LEFT
TCNU4120400	DENT	RIGHT
TCNU4120400	DENT	LEFT
TCNU4120400	BENT	LEFT
TCNU4120400	BENT	RIGHT
TCNU4527612	DENT	CORNERPOST
TCNU4878350	DENT	FRONT
TCNU4878350	DENT	LEFT
TCNU4878350	DENT	CORNERPOST
TCNU4878350	BENT	LEFT
TCNU4878350	DENT	RIGHT
TCNU4878350	BENT	RIGHT
TCNU4962008	BENT	FLOOR
TCNU6503590	BENT	LEFT
TCNU6503590	BENT	FLOOR
TCNU6884141	BENT	RIGHT
TCNU6884141	BENT	LEFT
TCNU7204871	SCRATCHED	RIGHT
TCNU8271046	HOLE	TOPROOF
TCNU8442426	BENT	RIGHT
TCNU8610514	DENT	CORNERPOST
TCNU8662858	BENT	RIGHT
TCNU8662858	DENT	RIGHT
TCNU8973171	BENT	RIGHT
TEMU1426892	BENT	FRONT

Without any liability accepted
Constantia Seaside Container Terminal
Planning Department

M. V. ANNIE B
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
TEMU1426892	BENT	LEFT
TEMU1426892	BENT	RIGHT
TEMU6978153	BENT	RIGHT
TEMU6978153	BENT	LEFT
TEMU8121940	DENT	CORNERPOST
TEMU8882343	BENT	LEFT
TEMU8882343	BENT	FLOOR
TGBU3780190	DENT	FRONT
TGBU3780190	BENT	LEFT
TGBU3780190	BENT	RIGHT
TGBU6630213	BENT	LEFT
TGBU6630213	BENT	FLOOR
TGBU6804927	DENT	RIGHT
TGBU6849412	DENT	LEFT
TGBU9320551	BENT	RIGHT
TGBU9320551	DENT	LEFT
TGBU9320551	BENT	LEFT
TGBU9320551	DENT	CORNERPOST
TGBU9320551	DENT	RIGHT
TGBU9662364	DENT	LEFT
TGBU9662364	DENT	CORNERPOST
TGHU9576170	BENT	LEFT
TGHU9662746	DENT	LEFT
TGHU9662746	BENT	LEFT
TGHU9662746	BENT	DOORSYSTEM
TGHU9662746	DENT	BACK
TGHU9662746	DENT	RIGHT
TGHU9662746	BENT	RIGHT
TGHU9662746	BENT	FRONT
TGHU9662746	CUT	LEFT
TGHU9850023	DENT	CORNERPOST
TIIU5872952	BENT	RIGHT
TLLU2219885	BENT	FRONT
TLLU2219885	BENT	CORNER

Without any liability accepted
Constantia South Container Terminal
Planning Department

M. V. ANNIE B
AKCO
CHIEF OFFICER

FOR RECEIPT ONLY
WITHOUT PREJUDICE

Container	Damage type	Damage location
TLLU2266038	DENT	FRONT
TLLU2266038	DENT	RIGHT
TLLU2266038	BENT	RIGHT
TLLU2266038	BENT	LEFT
TLLU2422491	BENT	LEFT
TLLU2422491	DENT	FRONT
TLLU2422491	DENT	RIGHT
TLLU2422491	BENT	RIGHT
TLLU2422491	DENT	LEFT
TLLU5116788	SCRATCHED	LEFT
TLLU5123832	BENT	LEFT
TLLU5123832	BENT	FRONT
TLLU5901287	DENT	RIGHT
TLLU5901287	CUT	LEFT
TLLU5901287	DENT	LEFT
TLLU5901287	BENT	LEFT
TRHU1405595	DENT	DOORSYSTEM
TRHU1405595	BENT	RIGHT
TRHU1405595	DENT	CORNERPOST
TRHU1405595	DENT	FRONT
TRHU1405595	DENT	RIGHT
TRHU1405595	DENT	LEFT
TRHU3816070	DENT	LEFT
TRHU3816070	BENT	FRONT
TRHU3816070	BENT	RIGHT
TRHU3847256	SCRATCHED	RIGHT
TRHU4043843	BENT	LEFT
TRHU4043843	BENT	RIGHT
TRHU4408200	DENT	RIGHT
TRHU4408200	DENT	LEFT
TRHU4429775	DENT	FRONT
TRHU4429775	DENT	LEFT
TRHU4429775	DENT	RIGHT
TRHU4500997	BENT	RIGHT

Container	Damage type	Damage location
TRHU4500997	BENT	LEFT
TRHU4805569	DENT	CORNERPOST
TRHU4845725	BENT	LEFT
TRHU4845725	BENT	RIGHT
TRHU4957284	BENT	LEFT
TRHU4957284	DENT	LEFT
TRHU5028062	BENT	LEFT
TRHU5028062	BENT	RIGHT
TRHU6897651	DENT	LEFT
TRHU7741370	BENT	RIGHT
TRHU7741370	BENT	LEFT
TRHU8281310	SCRATCHED	LEFT
TRLU7512259	BENT	RIGHT
UETU5701350	DENT	RIGHT
UETU5923933	DENT	RIGHT
UETU6953697	SCRATCHED	LEFT
UETU7292647	DENT	RIGHT
UETU8195235	BENT	LEFT
UETU8354450	SCRATCHED	RIGHT
UETU8550474	BENT	DOORSYSTEM
WNGU2693499	SCRATCHED	FRONT
WNGU2693821	DENT	FRONT

Without any liability accepted
Gensima South Container Terminal
Planning Department

M. V. ANNIE B
AKC
CHIEF OFFICER

Page 25 of 25
FOR RECEIPT ONLY
WITHOUT PREJUDICE